



## **AIRPORT COMMISSION STAFF REPORT**

**ITEM NO. 5.2**

**DATE:** October 6, 2025  
**TO:** Chairperson and Members of the Airport Commission  
**FROM:** Benny Stuth, Airport Manager  
**SUBJECT:** Aircraft Incident Report - August 2025

### **RECOMMENDED ACTION**

Staff recommends the Airport Commission receive information on an aircraft incident that occurred on August 15, 2025.

### **DECISION TYPE**

Administrative

### **SUMMARY**

This report summarizes an incident involving an aircraft landing on Runway 25R that occurred on August 15, 2025.

### **DISCUSSION**

On August 15, 2025, at 5:30 pm, an LVK tenant in a twin, Piper PA-34-200, landed on Runway 25R. Immediately following the landing, the nose gear collapsed. Airport staff assisted in the removal of the aircraft from the runway after the aircraft was released by National Transportation Safety Board personnel. Runway 25R was closed from approximately 5:30 pm until 9:00 pm. There were no injuries to the pilot, co-pilot or the one passenger on board. There was no damage to City property.

### **ATTACHMENTS**

Prepared by: Angela Hescher  
Administrative Technician